

St. Xavier's High School: Senior Secondary



Opp. Income Tax Office, Near L.V. prasad Eye Hospital, Ambapua, Brahmapur,
Dist.- Ganjam (Odisha) - 760 010

Affiliated to C.B.S.E., New Delhi

Affiliation No.: 1530073

School Code: 09718^{15488*}

Managed By: St. Francis Education Society UDISE Code: 21192500955

Ref No. ...SXHS/1225/2024

Date: ...17.04.2024...

To

The Deputy Secretary/Joint Secretary (Aff.)
CBSE Affiliation
Shiksha Kendra -2, Community Centre
Preet Vihar, Delhi-110092

Respected Sir,

Sub.: COMPLIANCE

Ref.: Application No. EX-90378-2324 dated 27/12/2022

Apropos to the subject and reference as stated above, respectfully we submit a statement of compliance for kind perusal.

S L · N O	REJECTION GROUND	SUBMISSION
01	The School is not enclosed with in 6feet height concrete boundary wall. The iron grills are fixed on concrete wall to make it 6 feet in the front side. The boundary wall is not in continuation, there is a gap seen near play ground. Moreover, all side boundary wall is not seen from the aerial view.	The School is enclosed above 7 (Seven) feet height concrete boundary wall. The iron grills are removed. The Boundary wall is in continuation. Inclusive of the play ground the school land is a single contiguous land surrounded by concrete boundary wall of Seven feet all around.
02	The playground is under developed and lots of construction materials are lying in the school campus near playground.	The play ground is well maintained. The construction materials are removed.
03	This school doesn't have the facilities for CWSN like ramp/lift to access upper floors. The school has not constructed separate CWSN	The school is committed to provide required facilities to CWSN. The lift is under construction and will be functional soon. Now there are CWSN toilets for boys and girls in ground floor and other floors are in under construction.



<p>Toilets for boys and girls in every floor and building blocks.</p>	
<p>04 As per data filled by the school, all the labs (Computer, maths, physics ,biology)are under sized and no composite lab. The school does not have fully equipped separate maths lab and composite lab for secondary level. The school has shown small and normal class rooms as ,maths lab and science lab. There is no proper equipment,demonstration table,work station in these rooms.Biology lab is under sized and under stocked.Proper demonstration tables and workstations are not available.The tables are placed adjacent to the wall is not as per norms. Chemistry lab does not have proper equipment/ apparatus, no proper demonstration table with fixture/installation and work stations. Gas cylinders are seen inside the chemistry lab which is unsafe. There is no exhaust fan, fire extinguisher and emergency exit in chemistry lab.</p>	<p>Computer, Maths,Physics and Biology Labs are of suitable size and are well equipped. There are well equipped Math Lab. and Composite Lab for Secondary Level. The Labs have demonstration table and workstation. Gas cylinders are safely placed. Exhaust fans , and fire extinguishers are installed.</p>
<p>05 The library books are not organize appropriately, it is looking like a store room. Reading space for student and staff is not as per norms .It is very congested.</p>	<p>There is a spacious library. There is a separate adjacent reading space for students and staff as per prescribed norms.</p>
<p>06 There is no partitions in urinal (both boys/girls).The toilets /urinals are not seen in every floors.</p>	<p>There are partitions in urinals (both boys & girls).Toilets and urinals are there in every floor.</p>
<p>07 The indoor sports is seen in a very small room and the sports facilities are inadequate.</p>	<p>Adequate indoor sports space is there.</p>
<p>08 The school have 2 building blocks however not mentioned in building safety and fire safety certificates. The building safety and fire safety</p>	<p>The Building safety certificate , safe-drinking water certificate, and sanitary and Fire safety certificate etc. as issued by the competent authority/authorities are submitted.</p>



certificates are not in prescribed format. The floors, blocks and validity periods are not mentioned in the certificates. The water and sanitation certificates are not in prescribed format. The school has obtained separate safe drinking water and sanitary certificate however the validity period is not mentioned in the certificates.



Respectfully we further submit that :

- i. The school is committed to comply with the prescribed norms and make good all deficiency.
- ii. The lift is under construction and will be operational soon

We humbly request your good office for a kind and sympathetic perusal of our application and a favorable action.

Yours faithfully;

Upatnaik
PRINCIPAL
PRINCIPAL
St. Xavier's High School Senior Secondary
BERHAMPUR (GM)

[Signature]
MANAGER
Manager
St. Xavier's High School
Berhampur (Gm.)



Xavier's High School: Senior Secondary



Opp. Income Tax Office, Near L.V. prasad Eye Hospital, Ambapua, Brahmapur,
Dist.- Ganjam (Odisha) - 760 010

Affiliated to C.B.S.E., New Delhi Affiliation No.: 1530073 School Code: 99718¹⁵⁴⁸³*

Managed By: St. Francis Education Society UDISE Code: 21192500955

Ref No. SXHS/A225/2024

Date: 17.04.2024.....

To

The Deputy Secretary/Joint Secretary (Aff.)
CBSE Affiliation
Shiksha Kendra -2, Community Centre
Preet Vihar, Delhi-110092

Respected Sir/Madam

We wanted to state that the compliances as required by C.B.S.E. for extension of Affiliation are almost completed.

1. Regarding the Boundary walls, the School premise was always enclosed with Seven Feet tall boundaries, but the entrance was constructed with Iron Rails attached for elevation. But as per the prescribed requirement, those rails are removed and concrete walls are continued for further safety.
2. Regarding the playground, the building materials seen at the video was for a pathway as during the rainy days the ground is unsafe for students walk in between two buildings. Those materials were immediately used and cleaned. The Campus do have an adequate outdoor play space.
3. Regarding CWSN, due to lack of space a new block is being constructed to accommodate CWSN toilets. Already the ground floor have an CWSN toilet for boys and girls. The building construction plan is being attached for further reference.
4. Regarding Laboratories, Computer, Maths, Physics and Biology Labs are of suitable size and are well equipped. There are well equipped Math Lab. and Composite Lab for Secondary Level. The Labs have demonstration table and workstation. Gas cylinders are safely placed. Exhaust fans, and fire extinguishers are installed.
5. Regarding Library, There is a spacious library. There is a separate adjacent reading space for students and staff as per prescribed norms.
6. Regarding partition in toilets, There are partitions in urinals (both boys & girls). Toilets and urinals are there in every floor.
7. Adequate indoor sports space is there.



8. The Building safety certificate , safe-drinking water certificate, and sanitary and Fire safety certificate etc. as issued by the competent authority/authorities are submitted.

Further we are attaching the Building Construction plan for LIFT and CWSN. The Construction is under full swing and we therefore request for kind consideration of time and we ensure, the work shall be completed as per the required and prescribed norms of CBSE. We humbly request your good office for a kind and sympathetic perusal of our application and a favorable action.

Thank You

Yours faithfully;

With Regards



Pratnaik
Principal
PRINCIPAL

St. Xavier's High School Senior Secondary
BERHAMPUR (GM)

A handwritten signature in black ink.

Manager

St. Xavier's High School
Berhampur (Gm.)



Specialist in Lift Technologies

Estimate No.: JET/013/24

Date: 27/02/2024

To,
St. Xavier's High School Sr. Sec
Ambapua, Berhampur, Odisha.

Dear Sir,

Sub: Supply, Erection & Maintenance of Passenger Lift G+2, at Berhampur, Odisha Site.

We thank you very much for the courtesy extended to the undersigned/Agent, when he called upon you. We take pleasure in furnishing our proposal to design, develop, supply, erect & maintain Passenger elevator at the above premises. Our offer is subject to terms & conditions, technical specification, builders work enclosed herewith.

Design:

These components and parts are specially design and developed to suit normal climatic and working conditions.

Validity

The amount quoted by us is valid for acceptance for a period of 30 days from the date of this offer.

Contract Amount

The Contract amount quoted is for complete execution to entire job as per the specification & contract Terms. The quoted amount is exclusive of all builders' work as per details given in our attached proposal.

We earnestly hope that you will find our offer very attractive and distinct one and favors us with your valuable orders.

Thanking you and assuring you of our best services at all times and looking forward to a long term business relationship, we remain.

Yours faithfully,

For JET ELEVATOR



Upatraik
PRINCIPAL

St. Xavier's High School Senior Secondary
BERHAMPUR (G.M.)

S. S. S. S.
Manager
St. Xavier's High School
Berhampur (Gm.)

Xavier's High School: Senior Secondary



Opp. Income Tax Office, Near L.V. prasad Eye Hospital, Ambapua, Brahmapur,

Dist.- Ganjam (Odisha) - 760 010

Affiliated to C.B.S.E., New Delhi

Affiliation No.: 1530073

School Code: 09718¹⁵⁴⁸⁸*

Managed By: St. Francis Education Society UDISE Code: 21192500955

Ref No. XSHS/A225/2024

Date: 17.09.2024



Upatnaik
PRINCIPAL

St. Xavier's High School Senior Secondary
BERHAMPUR (G.M.)

Gestland

Manager
St. Xavier's High School
Berhampur (Gm.)